





•




BODY ROTATES WITH RESPECT TO HEAD ABOUT A-AXIS












The state of the s








REPEATABLE POSITIONING OF MAICHINE

<u> 17.8.</u>













, t













PLANE #4, Z=44.0





F17.17.



SYNAMIC MACHINE ACCURACY IN XYPLANE

— 19.15.





PARAMETER	PARAMETER	ERROR
AFFECTING HOLE	TOLERANCE	CONTRIBUTION,
MISLOCATION	(INCH)	ΔS; (INCH)
POGO Y AND Z	0.012	0.0071
LOCATION		
FIXTURE SET POINT	0.010	0.0042
BLOCK Z ERROR		
C-AXIS OFFSET IN Y	0.003	0.0027
COMPOSITE TOOL	0.005	0.0021
LENGTH		
MACHINE Z ERROR	0.012	0.0101
MACHINE Y ERROR	0.012	0.0218
WAC AXIS Z ERROR	0.012	0.0051
WAC AXIS Y ERROR	0.005	0.0045
DELTA R BETWEEN	0.050	0.0120
POGOS		
PANEL ANGLE	1 DEGREE OVER	0.0005
CHANGE EFFECT	3 INCHES	
LOCATOR PIN ERROR	0.003	0.0027
DRILL C-AXIS OFFSET	0.002	0.0020
DRILL ENTRY	0.002	0.0020
WANDER		
	TOTAL ERROR,	0.0294
	ΔS	

-F19.20.